

Service Information

SERVICE TOOL (Ver.1.4.2.0) VERSION UPGRADE

- 1. Model Name
- 2. General
- 3. Description
- 4. Action

PN-UH861, PN-UH551, PN-UH501, PN-UH431 (for North America)

The version of the service tool has been upgraded.

Service Tool

[PN-UH861/UH551/UH501/UH431]

	Before change Version	⇒	After change Version	Comment
Service tool	1.3.2.1	⇒	1.4.2.0	
Main firmware	2.07	⇒	2.09	
LAN firmware	0.14	⇒	0.15	
TPC firmware	0.13	⇒	0.13	No change

[Item of change]

Major changes from the service tool Ver.1.3.2.1 previously released are as below:

1. For conformance to California security regulation:
The specification has been changed to request to change the password at the time of initial login.

[Note]

If AC power is turned OFF while opening the service menu, the setting of the color mode will be reset. Please close the service menu or turn the power OFF with the remote control or the button on the main unit before turning OFF AC power.

(For the field)

Please use the above tool as needed basis.

When the firmware rewriting is required due to the replacement of the PWB etc, please use the latest version

(For the inventory)

None

(For the production)

From March 2020 Production.

[PN-UH861/UH551/UH501/UH431]
 (Release history of the main firmware)

Version	Detail	Action
2.04	New release (for North America)	
2.05	Specification change so that the color correction of TINT/COLOR can be carried out with HDMI RGB	January 2019
	Change of the mode name of "Game" in COLOR MODE to "Thru"	
	Modification so that the operation guide of the remote control is displayed on the file browser of Media Player	
2.07	Correction of the trouble that the user's color mode setting will be reset when opening the service menu	March 2019
	Correction of the trouble that the noise will appear on the screen when opening the service menu while displaying the image of 4K60Hz	
2.09	Modification due to the conformance to California security regulations	March 2020

(Release history of the LAN firmware)

Version	Detail	Action
0.14	New release (for North America)	
0.15	Modification due to the conformance to California security regulations	March 2020

(Release history of the FRC firmware)

Version	Detail	Action
0.13	New release (for North America)	