

IMPORTANT Please note that you have to update the firmware of Luna2 Models
(MX-B468F/MX-B468P/MX-C358F/MX-C428P) to 230.216 first, then 230.217

Model Name	June 2023	Nov 2023	Jan 2024	May 2024	May 2024
MX-C357F	CXTZJ.221.204	CXTZJ.230.038	CXTZJ.230.207	<-	CXTZJ.230.217
MX-C407P	CSTZJ.221.204	CSTZJ.230.038	CSTZJ.230.207	<-	CSTZJ.230.217
MX-C407F/C507F	CXTAT.221.204	CXTAT.230.038	CXTAT.230.207	<-	CXTAT.230.217
MX-C507P	CSTAT.221.204	CSTAT.230.038	CSTAT.230.207	<-	CSTAT.230.217
MX-C557F/C607F	CXTPP.221.204	CXTPP.230.038	CXTPP.230.207	<-	CXTPP.230.218
MX-C607P	CSTPP.221.204	CSTPP.230.038	CSTPP.230.207	<-	CSTPP.230.218
MX-B557F/B707F	MXTGW.221.204	MXTGW.230.038	MXTGW.230.207	<-	MXTGW.230.217
MX-B557P/B707P	MSTGW.221.204	MSTGW.230.038	MSTGW.230.207	<-	MSTGW.230.217
MX-B427W	MXLBD.221.204	MXLBD.230.038	MXLBD.230.207	<-	MXLBD.230.217
MX-B427PW	MSLBD.221.204	MSLBD.230.038	MSLBD.230.207	<-	MSLBD.230.217
MX-B467F	MXTGM.221.204	MXTGM.230.038	MXTGM.230.207	<-	MXTGM.230.217
MX-B467P	MSNGM.221.204	MSNGM.230.038	MSNGM.230.207	<-	MSNGM.230.217
MX-C358F	CXTGV.221.204	CXTGV.230.038	CXTGV.230.207	CXTGV.230.216	CXTGV.230.217
MX-C428F/C528F	CXTMM.221.204	CXTMM.230.038	CXTMM.230.207	<-	CXTMM.230.217
MX-C428P	CSTGV.221.204	CSTGV.230.038	CSTGV.230.207	CSTGV.230.216	CSTGV.230.217
MX-C528P	CSTMM.221.204	CSTMM.230.038	CSTMM.230.207	<-	CSTMM.230.217
MX-B468F	MXTSN.221.204	MXTSN.230.038	MXTSN.230.207	MXTSN.230.216	MXTSN.230.217
MX-B468P	MSNSN.221.204	MSNSN.230.038	MSNSN.230.207	MSNSN.230.216	MSNSN.230.217

IMPORTANT Please note that you have to update the firmware of Luna2 Models
(MX-B468F/MX-B468P/MX-C358F/MX-C428P) to 230.216 first, then 230.217